



SANITIZER PARTS


Product Catalog 2022

BIOSHIELD® UV DISINFECTION STERILIZER

REPLACEMENT PARTS

Item	Part No.	Description
1	523035	50 Watt UV Lamp for Model #522635
1	523036	80 Watt UV Lamp for Model #522636
1	523037	120 Watt UV Lamp for Model #522637
1	523038	150 Watt UV Lamp for Model #522638 and #522945
2	523034	4-Pin Lamp Connector
3	523423	Lamp Spacer
4	411000	Black Retaining Nut
8	960533	Quartz Sleeve Gasket
9	523039	Quartz Sleeve 22.25" for Model #522635
9	523040	Quartz Sleeve 38.25" for Model #522636
9	523041	Quartz Sleeve 50.75" for Model #522637
9	523042	Quartz Sleeve 65.00" for Model #522638 and #522945
11	523110	50 Watt UV Sterilizer Housing
11	523111	80 Watt UV Sterilizer Housing
11	523112	120 Watt UV Sterilizer Housing
11	523113	150 Watt UV Sterilizer Housing
KITS		
	523460	Ballast Assembly Only with Flow Switch Input Model #522635 - 522637
	523462	Ballast Assembly Only with Flow Switch Input Model #522638/522945
	523461	Ballast Assembly with Flow Switch and Tee Model #522635 - 522637
	523463	Ballast Assembly with Flow Switch and Tee Model #522638/522945
	523382	Quartz Sleeve Module - All Models (Includes Item # 5, 8)
	410020	Union Assembly for Models # 522935-522638 (3"/2.5" - Includes Item # 12, 13, 14, 4)
	523148	Union Assembly for Models # 522638-522945 (3") *
	523383	Seal Kit - All Models (Includes Item # 8, 12)
	410016Z	Seal Kit Union (Includes 2 of Item #12)

*REVISION 2




CALIFORNIA PROPOSITION 65 WARNING
 ⚠️ **WARNING:** Cancer and Reproductive Harm.
 ⚠️ **AVERTISSEMENT:** Peut Causer le Cancer et des Dommages au Système Reproducteur.
 ⚠️ **ADVERTENCIA:** Cáncer y Daño Reproductivo.
www.p65warnings.ca.gov PK 201714

Product on page 243.

AUTOMATIC FEEDER - MODEL 300, 302, 300-19, 300-29

REPLACEMENT PARTS



Item	Qty.	Part No.	Description
Order No.:		R171016	R171026
Model No.:		300	302
Description:		AUTOMATIC FEEDER	SPA HOT TUB FEEDER

1	1	R172008W	3 in. threaded cap, white
2	1	R172009Z	O-ring, cap
3	Opt.	R172020	Check valve Old Style
5	1	R172023Z	3/8 in. o.d. x 1/4 in. i.d. tubing, 8 ft.
9	2	R172032Z	Tube fitting with compression nut
10	2	R172033Z	Gasket
11	2	R172034Z	Saddle clamp
14	1	R172037	Spa chamber #302 only
17	Opt.	R172052	Cap wrench
18	1	R172060Z	Control valve 1/4 in. NPT x tube with compression nut
19	1	R172036Z	Silicone lubricant, 3/4 oz.
20	1	R172061Z	Combination check valve / elbow
21	Opt.	R172080Z	Flow indicator w/check valve
23	Opt.	R172288	1-1/2 in.-2 in. Corrosion resistant check valve
24	Opt.	R172323	1/4 in. Corrosion resistant check valve
25		R172061ZB	Standpipe adapter, Bromine
26		R18761	6 in. Standpipe 3/8 in. o.d. x 1/4 in. i.d.
27	1	R18706Z	Compression nut only

Order No.: R172064


Parts bag for 300, 302, 300-19 & 300-29

9	2	R172032Z	Tube fitting with compression nut
10	2	R172033Z	Gasket
11	2	R172034Z	Saddle clamp
18	1	R172060Z	Control valve 1/4 in. NPT x tube with compression nut
19	1	R172036Z	Silicone lubricant
20	1	R172061Z	Combination check valve / elbow

CALIFORNIA PROPOSITION 65 WARNING
 ⚠️ **WARNING:** Cancer and Reproductive Harm.
 ⚠️ **AVERTISSEMENT:** Peut Causer le Cancer et des Dommages au Système Reproducteur.
 ⚠️ **ADVERTENCIA:** Cáncer y Daño Reproductivo.
www.p65warnings.ca.gov P8-2017-14

AUTOMATIC FEEDER - MODEL 320

REPLACEMENT PARTS



CALIFORNIA PROPOSITION 65 WARNING
 ⚠️ **WARNING:** Cancer and Reproductive Harm.
 ⚠️ **AVERTISSEMENT:** Peut Causer le Cancer et des Dommages au Système Reproducteur.
 ⚠️ **ADVERTENCIA:** Cáncer y Daño Reproductivo.
www.p65warnings.ca.gov


Item	Qty.	Part No.	Description
Order No.: R171096			
Model No.:		320	
Description:		IN-LINE AUTOMATIC FEEDER	
1	Opt.	R172052	Cap wrench
2	1	R172008W	3 in. threaded cap - white
3	1	R172009Z	O-ring, cap
4	1	R172321	#320 Body only (new style)
5	1	R01052	Lock screw
6	1	R172248Z	Check valve
7	1	R172317	Diverter tee 1-1/2 NPT x 2 in. slip
8	1	R172256Z	1/2 in. x Short MPT nipple
9	1	R172086Z	1/2 in. Control valve
10	2	R172272Z	1/2 in. NPT x tube 90° ELL w/nut
10	Opt.	R172274Z	Compression nut only (for R172272Z)

Item	Qty.	Part No.	Description
11	1	R172091	5/8 in. o.d. Short feeder tube
11	Opt.	R171097Z	Tube support spring
12	2	R172210	2 in. x 1-1/2 in. S x S bushing for 1-1/2 in. PVC only ¹
13	Opt.	R172037	Spa chamber
14	1	R172036Z	Silicone lubricant, 3/4 oz.
15	1	210396Z	Screen
16	1	R172134	1/2 in. NPT PVC plug
17	1	R172253Z	5/8 in. o.d. 18 in. tube (optional top feed)
18	1	R172319Z	Bottom O-ring
19	Opt.	R172288	1-1/2 in. Corrosion resistant check valve
20	1	R172048B	Standpipe adapter, Bromine

¹ Not used with 2 in. PVC.

AUTOMATIC FEEDER - MODEL 322

REPLACEMENT PARTS



Item	Qty.	Part No.	Description
Order No.: R171100			
Model No.: 322			
Description: IN-LINE FEEDER			
1	Opt.	R172052	Cap wrench
2	1	R172008W	3 in. threaded cap, white
3	1	R172009Z	O-ring, cap
5	1	R01052	Lock screw
6	1	R172331	Check valve w/ restrictor
7	1	R172317	Diverter tee 1-1/2 NPT x 2 in. slip x slip
8	1	R172256Z	1/2 in. x Short MPT nipple
9	1	R172086Z	1/2 in. Control valve
10	2	R172272Z	1/2 in. NPT x tube 90° ELL w/nut

Item	Qty.	Part No.	Description
10A	Opt.	R172274Z	Compression nut only (for R172272Z)
11	1	R172091	5/8 in. o.d. short feeder tube
11	1	R171097Z	Tube support spring
12	2	R172210	2 in. x 1-1/2 in. S x S bushing (for 1-1/2 in. PVC only) ¹
13	1	R172258	Chemical chamber
14	1	R172036Z	Silicone lubricant, 3/4 oz.
15	1	R172007	1/4 in. NPT plug
16	1	R172319Z	Bottom O-ring
17	Opt.	R172288	1-1/2 in.-2 in. Corrosion resistant check valve
18	1	210396Z	Screen

¹ Not used with 2 in. PVC.


CALIFORNIA PROPOSITION 65 WARNING

⚠ **WARNING:** Cancer and Reproductive Harm.
 ⚠ **AVERTISSEMENT:** Peut Causer le Cancer et des Dommages au Système Reproducteur.
 ⚠ **ADVERTENCIA:** Cáncer y Daño Reproductivo.

www.p65warnings.ca.gov
PR030714A

HIGH CAPACITY AUTOMATIC FEEDERS MODELS HC-3315, HC-3330, HC-3340

REPLACEMENT PARTS



Item	Qty.	Part No.	Description
Order No.: R171215, R171230, R171240			
Model No.: HC-3315, HC-3330, HC-3340			
Description: HIGH CAPACITY AUTOMATIC FEEDER			
1	1	R172214	Lock ring
2	1	R172385D	Lid assembly complete
3	1	R172224XZ	Vent valve
4	1	R172221Z	O-ring vent valve
5	1	R172240Z	O-ring lid to housing
6	1	R172375	Lock screw
7	1	R172374	Lock spring
8	1	R175251	Screen
8A	1	R171919	Check Valve Seat
9	1	R172435	Check ball
11	2	R270484	1 in. Close nipple
12	1	R270531	1 in. Threaded union
13	1	R172439	Control valve
14	1	R172036Z	Silicone lubricant, 3/4 oz.
15	Opt.	R172288	1-1/2 in.-2 in. Check valve
16	1	R175009	Hose Bib w/t Handle 1/2 in.
17	1	R172134	1/2 in. threaded plug
NOT SHOWN			
		R172082	Flow rate indicator


CALIFORNIA PROPOSITION 65 WARNING

⚠ **WARNING:** Cancer and Reproductive Harm.
 ⚠ **AVERTISSEMENT:** Peut Causer le Cancer et des Dommages au Système Reproducteur.
 ⚠ **ADVERTENCIA:** Cáncer y Daño Reproductivo.
www.p65warnings.ca.gov


EXTENSIONS / DISPENSERS / FLOW INDICATORS

REPLACEMENT PARTS


Item	Qty.	Part No.	Description
Order No.: R172087 10 IN. EXTENSION COMPLETE			
Order No.: R172283 20 IN. EXTENSION COMPLETE			
1	1	R172078	Lockscrew (bottom collar)
2	1	R172009Z	O-ring
Order No.: R172080Z Description: FLOW INDICATOR			
1	1	R172392	Access plug 1/4 in. MPT
2	1	R172393	O-ring
3	1	R172020	Check valve
4	1	R172235	Marker clip
Order No.: R172627 Description: CORROSION RESISTANT FLOW INDICATOR			
1	1	R172276	Commercial flow indicator
1A	1	R172313	1/2 in. Coupling (included with flow indicator)
2	1	R270422	1/2 in. x 90° Elbow FPT
3	1	R172272Z	1/2 in. x 90° NPT x tube fitting with nut
4	1	R172628	Saddle clamp with inlet fitting (threaded)
5	1	R172263Z	Saddle gasket
6	1	R172324	1/2 in. Corrosion resistant check valve. Tube x tube
Order No.: R171086 Model No.: 330 Description: FLOATING DISPENSER			
1	1	R18729B	Lid only (new style – fits 'B' body)
Order No.: R171130 Description: SPLASHER POOL/SPA DISPENSER			
1	1	R18902	Cap
Order No.: R171090 Model No.: 335 Description: SPA OR SMALL POOL FLOATING DISPENSERS			
1	1	R18855	Screen
1	1	R18819	Lock ring





R172087 R172283




R172080Z



R171086



R171090



R172627

CALIFORNIA PROPOSITION 65 WARNING

⚠ **WARNING:** Cancer and Reproductive Harm.
 ⚠ **AVERTISSEMENT:** Peut Causer le Cancer et des Dommages au Système Reproducteur.
 ⚠ **ADVERTENCIA:** Cáncer y Daño Reproductivo.
www.p65warnings.ca.gov